Fire Risk Assessment -March 2018-



Broadhurst School

Ace Fire 14 Concorde Road Norwich NR6 6BW





Index:

Property Information	Page 3
Statement of the Fire Risk Assessment	Page 4
Scope of the Fire Risk Assessment	Page 5
General Information	Page 6
Fire Hazards and Their Elimination or Control	Page 7
Fire Protection Measures	Page 9
Management of Fire Safety	Page 11
Photo Library	Page 14
Level of Fire Risk	Page 15
Action Plan Colour Coding Reference	Page 17
Action Plan	Page 18
Example of a Fire Safety Maintenance Check List	Page 19
Emergency Plan Bullet Points	Page 20
Fire hazards, elimination or control measures and relevant codes of practice	Page 21
Notes	Page 24

Property Information	
Property Address	Broadhurst School, 19 Greencroft Gardens, London, NW6 3LP.
Name of responsible person/persons	Mr B Berkerv.
Site Manager	Mr B Berkery & Mrs Sylvester.
Areas of assessment	All areas & rooms within no.19 and the basement area of no.21 Greencroft Gardens.
Building type & construction	Single occupancy semi-detached building dating back to the 1890's with various conversions since. Constructed from traditional and modern materials.
Significant changes since last fire risk assessment.	The administration (offices) areas have been relocated to the basement areas of No. 21. The vacant room at the top of the school is now occupied by the Reception class, maximum of 20 pupils. Due to these changes the emergency evacuation plans have been reviewed and rewritten. Further comments on the above are made within this report.
Number of floors	5.
Date of previous risk assessment	January 2017.
Assessment carried out & prepared by: Tim Redman of Ace Fire. 26/03/18.	
Peer Reviewed by:	
John Sadler of Ace Fire. 11/04/2018.	
Sadler.	
Recommended date for review	March 2019.

Statement of the Fire Risk Assessment

This risk assessment is made under the requirements of the Regulatory Reform (Fire Safety) Order 2005 and where necessary guidance, recommendations and instruction has been taken, and quoted, from; The British Standards, The Buildings Regulations Part B 2010, Health & Safety at Work Act 1974, Management of Health & Safety at Work Regulations 1999, Electricity at Work Regulations 1989, Provisions and Use of Work Equipment Regulations 1998, The Housing Act 2004 and from a series of publications issued by Department for Communities and Local Government (DCLG) Fire Safety Risk Assessment guides and industry recognised guides such as Local Authorities Coordinators of Regulatory Services (LACoRS) "Housing – Fire safety" and the Local Government Group "Fire safety in purpose-built blocks of flats".

The potential hazards and/or risks identified (if any) in each section of this document increase the risk to life and/or property safety in and around the areas assessed.

The additional controls, recommendations and actions given for each section of the action plan/summary section of the document should be dealt with accordingly in order to bring the assessed areas up to the required standard and to reduce the risk to a level which is acceptable in the circumstances.

Additionally, in accordance with The Regulatory Reform (Fire Safety) Order 2005, the responsible person/persons must, among other things 'provide his employees with comprehensive and relevant information on the risks to them identified by the risk assessment, the preventative and protective measures to take and the procedures and measures which are in place for serious and imminent danger.

Before employing a child, the responsible person/persons must provide the parents of the child, among other things, with comprehensive and relevant information on the risks to that child identified by the risk assessment, the preventative and protected measures taken and the procedures and measures which are in place for serious and imminent danger.

The responsible person/persons must also co-operate with other relevant responsible persons (sharing the same occupancy) and inform them of relevant risks in his undertaking.

Where appropriate and necessary the assessment has included the consideration of sections 1-6, 8, 9 and 11 of the Dangerous Substances and Explosive Atmospheres Regulations 2002 (DSEAR) and other legislation relevant to the premises.

The risk assessment should be available for inspection or validation by any authorized person and should be reviewed:

Following a change of work practice,

Following a significant change of staffing level,

Following any structural or material change to the premises or processes conducted,

Following any change in the fire precautions in the premises,

Following any near miss or fire incidents,

At recommended intervals of no more than 12 months,

The purpose of this report is to provide an assessment of the risk to life in these premises, and, where appropriate to make recommendations to ensure compliance with fire safety legislation. The report does not address the risk to property or business continuity from fire.

Scope of the Fire Risk Assessment

In relation to the prevention and management of fire within these premises the following subjects are examined in this report:

- Means of escape from the premises.
- Fire exit & other fire safety signage.
- Means of raising the alarm.
- Emergency Lighting.
- Emergency Plans.
- Firefighting Equipment.

- Risk of Arson.
- Electrical appliance safety.
- Staff training.
- Compartmentation.
- Fire safety management.
- Fire detection & warning.

Note:

Whilst carrying out this fire risk assessment we will highlight any matters for concern that is discovered during the course of the assessment. It must be born in mind however that we can only report on what is found at the time of carrying out the assessment. Potential fire risks may well be different now than at the time of the risk assessors first visit audit and preparation of the report.

The fire risk assessment has been carried out as Type-1 Non-Destructive and cannot/should not be used as the building's structural inspection report or survey, if required such arrangements should be carried out by a competent person, namely a qualified building inspector.

A Type 1 fire risk assessment is the basic fire risk assessment required for the purpose of satisfying the Fire Safety Order (FSO). The inspection of the building is non-destructive. Where there are demountable false ceilings it may be appropriate to lift a sample of readily accessible false ceiling tiles. In addition, it will normally be appropriate to open a sample of service risers, provided access is practicable at the time of inspection. Unless there is reason to expect serious deficiencies in structural fire protection – such as inadequate compartmentation, or poor fire stopping – a Type 1 inspection will normally be sufficient for most premises. Where doubt exists in relation to these matters, the action plan of a Type 1 fire risk assessment may recommend that one of the other types of fire risk assessment be carried out or that further investigation be carried out by specialists. (However, this should not be a generic recommendation of all Type 1 fire risk assessments; the recommendation should be based on identification of issues that justify reason for doubt.)

The aim of this document is to assess fire risks within the building in order to protect persons working, residing and visiting the property including any contractor carrying out work at the building.

It is the duty of the person/persons deemed responsible for the property to ensure that the necessary requirements are met.

	General Information			
1	The Premises			
1.1	Number of floors	5.		
1.2	Approximate floor area (m2)	1100m ²		
1.3	Brief details of construction	Built in the 1890's and developed over recent years, constructed from brick, concrete, plasterboard timber.		
1.4	Use of premises	Education premises for children from the ages 2 ¹ / ₂ - 4 ¹ / ₂ years.		
2	The Occupants			
2.1	Approximate maximum number	139. 117 children + 22 staff.		
2.2	Approximate number at any one time	139.		
2.3	Maximum number of members of public	None usually, except parents dropping and picking up their children.		
2.4	Associated times of occupation.	Mon-Fri 08.00 – 19.00 (the caretaker is the only occupant within the school until 7pm)		
3	Occupants at risk from fire			
3.1	Sleeping occupants	None.		
3.2	Disabled occupants	There are no disabled members of staff or pupils.		
3.3	Occupants in isolation	No.		
3.4	Young persons	The school accommodates for children between the ages of $2\frac{1}{2} - 4\frac{1}{2}$ years.		
3.5	Others	Contractors and visitors by appointment only.		
4	Fire loss experience	None.		
5	Other relevant information.	None.		
6	Relevant fire safety legislation			
	The following fire safety legislation applies to these premises.	Regulatory Reform (Fire Safety) Order 2005.		
	The above legislation is enforced by.	London Fire And Rescue Services.		
	Other legislation that makes significant requirements for fire precautions in these premises (other than the building regulations 2010).	Health & Safety at Work Act 1974. Management of Health & Safety at Work Regulations 1999. The Office for Standards in Education, Children's Services and Skills (ofsted). Electricity at Work Regulations 1989. Provisions and Use of Work Equipment Regulations 1998.		

	Fire Hazards and Their Elimination or Control		
7.	Electrical sources of ignition	Yes	No
7.1	Reasonable, measures taken to prevent fires of electrical origin?	✓	
7.2	More specifically:		
	Fixed installations periodically tested?		✓
	Portable appliance testing up to date?		✓
	Suitable policy regarding the use of portable electrical appliances?	\checkmark	
	Suitable use of trailing leads and sockets/adapters?	\checkmark	
7.3	Comments and potential hazards:		
	The fixed electrical installations appear to be in a good working order, the last safety		
	inspection/test, in accordance with the IEE Wiring Regulations (BS7671), was carried out		
	in 2011. The next inspection was due in 2016, there is no evidence to suggest that this had		
	taken place.		
	Portable electrical appliance testing (P.A.T) was last undertaken in September 2016 by		
	Cambs–Pat (uk) Ltd. In order to maintain the electrical appliances correctly it is		
	recommended that P.A.T is carried out in 2018.		
0	Trailing and extension leads, where appropriate, are used in good order.		
ð.	Smoking		
8.1	Are measures taken to prevent lires as a result of smoking?	v	
0.2	Smalting machibited on these memices?	1	
	Smoking prohibited in appropriate group?	•	
	Suitable arrangements for those who smoke?		
	Were these arrangements observed at the time of the assessment?	-	√
83	Comments and potential hazards:		-
0.5	"No Smoking" signs are displayed. It is regarded and widely known that smoking is		
	prohibited within public places and workplaces.		
9.	Arson		
9.1	Does the security against arson appear satisfactory?	✓	
9.2	Are the boundaries and exterior of the premises free from unnecessary combustibles?	✓	
9.3	Comments and potential hazards:		
	The security of the premises is satisfactory and there has been no recent history of arson or		
	vandalism in the surrounding area.		
10.	Heating installations including portable heaters		
10.1	Are portable heaters in use?		✓
10.2	If portable heaters are used:	NA	NA
	Are hazardous types used (e.g. LPG or radiant bar heaters)?	NA	NA
	Are measures taken to reduce the risk of ignition of combustible materials?	\checkmark	
10.3	Is the maintenance of the fixed heating installations up to date?	\checkmark	
10.4	Comments and potential hazards:		
	The building is heated by way of central heating radiators and an electrical airflow system,		
	the boilers are located in the family interview room of no.21 and within the outside service		
	cupboard. The Gas Safety inspection and test was carried out in June 2016 by Waterfront		
	Development, there is no certificate of inspection to indicate that the maintenance is up to		
11	date.		
11.	Cooking	1	
11.1	Are sale cooking practices adhered to?	•	
11.2	Are filters changed and ductwork cleaned regularly?	NA	NIA
	Are appropriate extinguishers available?		INA
113	Comments and potential hazards:		
11.3	Comments and potential nazarus. Basic kitchen appliances in use: oven microwave kettle all of which are in good		
	condition The kitchen is located in the basement area of no 21 Greencroft Gardens		
	Firefighting equipment is located in the entrance lobby and a fire blanket sited in the		
	kitchen.		

	Fire Hazards and Their Elimination or Control (continued)		
12.	Housekeeping	Yes	No
12.1	Is the standard housekeeping adequate?	✓	
12.2	More specifically:		
	Are combustible materials kept away from ignition sources?	✓	
	Is there a buildup of combustible or waste material?		✓
	Are hazardous materials/substances stored correctly?	✓	
	In general is the storage of combustibles satisfactory?	✓	
	Comments and potential hazards:		
	It is typical of this type of premises that there will always be a certain level of Class A		
	combustibles (paper, cardboard, textiles etc.).		
	Upon inspection it was noted that care is taken not to store combustible materials close to		
	sources of heat.		
	The overall standard of housekeeping and storage is good.		
13.	Outside contractors and building works		
13.1	Are fire safety policies imposed on outside contractors?	 ✓ 	
13.2	Is there adequate control in reference to work carried out by outside contractors which may	 ✓ 	
	include hot works?		
13.3	If there are in-house maintenance personnel, are preventive measures taken during any hot works?	~	
13.3	Comments and potential hazards:		
14.	Dangerous substances		
14.1	Are there adequate fire precautions in place which are associated with dangerous substances within the premises?	NA	NA
14.2	If "Yes" to 14.1 has a suitable risk assessment been carried out, in accordance with the	NA	NA
	Dangerous Substances and Explosive Atmospheres Regulations 2002?		
14.3	Comments and potential hazards:		
15.	Other significant fire hazards		√
15.1	Hazards:		
15.2	Comments and potential hazards:		

	Fire Protection Measures		
16.	Means of escape from fire	Yes	No
16.1	It is considered that the premises are provided with reasonable means of escape from fire.	✓	
16.2	More specifically:		
	Adequate design of escape routes?	✓	
	Adequate provision of exits?	✓	
	Exits easily and immediately operable where necessary?		\checkmark
	Fire exits open in the direction of escape where needed?	✓	
	Avoidance of sliding or revolving doors as fire exits where appropriate?	✓	
	Satisfactory means for securing exits?	✓	
	Reasonable distances of travel:	✓	
	• Where there is a single direction of travel?	✓	
	• Where there are alternate means of escape?	✓	
	Suitable protection for escape routes?		✓
	Suitable fire precautions for all inner rooms?	✓	
	Escape routes unobstructed?	✓	
16.3	It is considered that the premises are provided with reasonable arrangements for means of	✓	
	escape for disabled persons?		
16.4	Comments and potential hazards:		
	There are two possible escape routes from all floors. However in order to maximize the		
	available evacuation time and reduce congestion on the escape routes all classrooms have		
	been given designated exit routes to follow (see notes page for breakdown).		
	Any pupil or staff member whom may require assistance will be appointed a "buddy" in		
	the event of an evacuation, this would have been pre-determined in a Personal Emergency		
	Evacuation Plan (PEEP), currently there are no pupils or staff that would require a PEEP.		
	The external exit gate along the side passage has a sliding bolt fitted and a mortice lock		
	reinstated. It appears that the gate is kept locked at all times. As the side passage forms an		
	integral part of the escape route the final exit, in this case the gate, must be able to be		
	opened without the use of a key in order not to delay the egress. With this in mind it is		
	recommended that during the day the gate is kept locked by way of the sliding bolts only.		
	The fire exit door to the metal stairway from the Reception Classroom is in need of repair,		
	in its current condition the full opening capacity cannot be achieved. See picture 1.		
17.	Measures to limit fire spread		
17.1	It is considered that there is:		
	• Compartmentation of a reasonable standard.	\checkmark	
	• Reasonable limitations of linings that may promote fire spread.	\checkmark	
17.2	Upon inspection it appears that fire dampers are provided to protect the means of escape	NA	NA
	against the spread of fire, smoke and combustion materials in the early stages of fire.		
17.3	Comments and potential hazards:		
	Compartmentation between each floor cannot be achieved, the circulation areas and		
	stairways are all open plan with no separation.		
	Fire doors are fitted to the third floor area only. All of the doors leading onto the escape		
	route are of solid pine construction with rebate panels, vision panels have now been fitted		
	into all of the classroom doors, these doors will provide some protection in the event of a		
	fire but do not appear to comply with the current fire door standards (BS476). Although		
	the best recommendation would be to upgrade the door sets to FD30 (30 minute fire doors)		
	it is my opinion that with the current fire precautions, rehearsed emergency plans in place		
	and improvements to the escape routes (external stairway) the existing doors are		
	acceptable, if the number of pupils significantly increases or the overall risk heightens then		
	the provision of fire doors would be strongly recommended. Applies to section 16 also.		

	Fire Protection Measures (continued)			
18.	Emergency escape lighting	Yes	No	
18.1	Reasonable standard of emergency lighting within the premises?	\checkmark		
18.2	Comments and potential deficiencies:			
	The building benefits from the installation of emergency backup lighting covering the			
	escape routes, stairs and final exits. There is a good source of natural and borrowed			
	lighting.			
19.	Fire safety signage			
19.1	Reasonable standard of fire safety signs and notices?	✓		
19.2	Comments and potential deficiencies:			
	There are fire action notices displayed on each floor and in the classrooms within the			
	building.			
	Fire exit directional signs are displayed along the escape routes all the way to the final exit.			
	The alternate fire exit within the office area (No. 21) should be identified by displaying an			
	appropriate sign, See picture 2.			
20	Means of giving warning in case of fire			
20.1	Reasonable manually operated fire alarm system provided?	✓		
20.2	Automatic fire protection provided?	✓		
20.3	Is the automatic fire detection appropriate for this type of premises and fire risk?	✓		
20.4	Are the associated devices in good condition and free from obstruction?	✓		
20.5	Remote transmission of alarm signal?		✓	
20.6	Comments and potential deficiencies:			
	There is Automatic Fire Detection (AFD) within the building consistent of that to a Grade			
	L4. Smoke detectors are located along the escape routes with a heat sensor in the kitchen,			
	manual call points (Break Glass Box) are provided on each floor and within the classrooms			
	which have access to the external stairway, and electronic fire bells are present on all floors			
	with the control panel on the ground floor entrance lobby.			
21	First Aid Firefighting equipment.			
21.1	Reasonable provision of portable fire extinguishers?	✓		
21.2	Are hose reels provided?		✓	
21.3	Are fire extinguishers easily accessible?	✓		
21.4	Are firefighting appliances appropriately signed?		✓	
21.5	Comments and potential deficiencies:			
	Fire extinguishers are provided on all floors to tackle small fires involving Class A			
	combustibles and fires of electrical origins.			
	The majority of extinguishers are wall mounted and signed.			
	The carbon dioxide (co2) extinguisher at the fire point on the third floor should be wall			
	mounted and the extinguishers within the office should have their brackets raised, See			
	picture 2. The fire extinguishers within the office require identification signs to be			
	displayed, See picture 3.			
	All of the fire extinguishers within the main school area are sited lower than usual, this has			
	been done to protect the children from possible injury from a falling extinguisher.			
22	Relevant automatic fire extinguishing system			
22.1	Type of system:	NA	NA	
22.2	Comments:			
23	Other relevant fixed systems and equipment			
23.1	Type of fixed system:	NA	NA	
23.2	Comments			
23.3	Suitable provision of fire-fighting switch for high voltage luminous tube signs, etc.	NA	NA	
23.4	Comments:			

	Management of fire safety		
24	Fire safety procedures	Yes	No
24.1	Fire safety is managed by: Mr Berkery & Mrs Sylvester.		
24.2	Competent persons appointed in undertaking general fire precautions are Mr Berkery &		
	Mrs Sylvester.		
24.3	Are fire safety arrangements recorded?	✓	
24.4	Appropriate fire procedures (emergency plans) in place?	✓	
	More specifically:		
	Are these procedures appropriate for the building type and use?	✓	
	Are procedures in the event of a fire documented?	\checkmark	
	Are there adequate arrangements for contacting the fire and rescue service?	\checkmark	
	Are there adequate arrangements in place to meet the fire and rescue service upon arrival	\checkmark	
	and provide information that may include hazards to fire fighters?		
	Are there arrangements in place in ensure that the premises have been evacuated?	✓	
	Are there suitable fire assembly points?	\checkmark	
	Are there provisions in place to aide disabled people in an evacuation?	\checkmark	
	Comments:		
	The emergency plans for the school are detailed and easy to follow, each classroom has a		
	copy along with details of their escape routes to take. Previously it was the duty of the		
	office staff coming down from the top floor to make a sweep of the building, now that the		
	layout of the building has changed this process cannot be achieved. With this in mind it is		
	recommended that the means for ensuring that each floor is evacuated should be renewed		
	and a more effective measure should be sought. It would be my recommendation that each		
	floor is allocated a fire marshall who is responsible for carrying out a sweep prior to		
	continuing their evacuation.		
	The evacuations plans were last reviewed in 2017.		
24.5	Persons trained in the use of fire extinguishers.		
	All staff have received fire extinguisher training.	✓	
24.6	Persons nominated and trained to assist with evacuation.		
	All teaching staff will assist their own class and Mr Berkery and Mrs Sylvester along with		
	the administrator will assist others.		
24.7	Routine in house inspections of fire safety precautions.	✓	
	Comments:		
	Matters relating to fire safety are overseen by the responsible persons.		
25	Training and fire drills.		
25.1	Are all staff given fire safety instruction and training on induction?	v	
	Comments:		
25.2	Staff training is carried out annually and at induction.		
25.2	Is all fire safety training given at suitable intervals?	v	
	Comments:		
25.2	Fire safety training is provided every 12-24 months.		
25.3	Does all fire training provide information, instruction or training on the following:		
	Fire risks in the premises?	•	
	The fire safety measures in the premises?	•	
	What to do in the event of a fire?	v	
	What to do on hearing the fire alarm?	√	
	How to raise the alarm?	√	
	Correct use of fire extinguishers?	√ √	
	Means for calling the fire rescue services?	√	
	Identity of nominated fire wardens?	√	
	Identity of persons nominated to use firefighting equipment?	✓	
	Comments:		
	All training is thorough and applicable to the requirements above. It has been indicated		
	that the last full fire safety training was carried out in 2014.		

	Management of fire safety (continued)		
	Training and fire drills (continued)	Yes	No
25.4	Are fire wardens given additional training in accordance with their role?	\checkmark	
	Comments:		
	Fire warden training was carried out in 2014. With the introduction of new staff it is		
	recommended that fire training is scheduled for all those nominated as fire wardens both		
	existing and new.		
25.5	Are fire drills carried out at sufficient intervals?	✓	
	Comments:		
	Two fire drifts were carried off 5 "November 2017. 1) $10.25am = 25$ start were present evenuetion timed at 4.17 min from activation to final call call -2) 2.15 mm = 23 staff		
	evacuation time at 4.17 min from activation to final folloating issues were present with the evacuation time recorded at 2.32 min, the following issues were		
	documented:		
	"some staff had not signed in Class 5 not use to using fire escape stairs outside so it		
	took longer than expected. Gate outside locked. Visitor book not thought of. Reception		
	class left with just one adult to help them down. Pawel not signed in along with Kenith +		
	Mr Berkerly. Fire door in reception won't open from outside once closed. Class 7		
	cannot hear alarm clearly"		
	The incidents recorded were not mentioned in the afternoon drill.		
	Hopefully the delays recorded were an isolated occurrence however if the time continues		
	to increase or remains around 4 minutes further investigation should be carried out and		
	Improvements made.		
25.6	Fire drills are carried out each term.	<u> </u>	
23.0	Is there employee of another employer carry out work in the premises:		
	safety?	•	
	Are these employee's provided with sufficient instruction and information relating to the	\checkmark	
	fire risks and fire safety?		
	Comments:		
	As far as it is appropriate any employee from an outside source that shall be working		
	within the building for a period of time shall be provided with details of the fire safety		
	arrangements.		
	This is not the case for contractors carrying out small repairs or maintenance, the		
26	responsible person/persons would be responsible for their wellbeing and safety.		
26.	Testing and maintenance		
20.1	Adequate maintenance of premises?	·	
	The building is of reasonable appearance and in a satisfactory condition for its age		
26.2	Weekly testing and periodic servicing of the fire alarm system?	\checkmark	
	Comments:	+	
	Weekly tests carried out and documented by the caretaker and the annual maintenance is		
	provided by Chubb Fire December 2017 (Bi-annual testing).		
26.3	Monthly and annual testing of emergency escape lighting?	\checkmark	
	Comments:		
	Carried out monthly and documented by the caretaker. Maintained annually by Chubb		
	Fire.		
26.4	Annual maintenance fire extinguishers?	↓	
	Comments:		
265	Last serviced in December 2017 by Chubb Fire. In accordance with BS5306.		
20.5	Comments:		
	All staff are encouraged to check the escape routes as they go about their daily duties		
1	1 m starr are encouraged to encer the escape routes as they go about their daily duties.	1	1

	Management of fire safety		
	Testing and maintenance (continued)	Yes	No
26.6	Six monthly inspection and annual testing of any rising mains?	NA	NA
	Comments:		
26.7	Weekly and monthly testing, six monthly inspection and annual testing of any	NA	NA
	firefighting lifts?		
	Comments:		
26.8	Weekly testing and periodic inspection of sprinkler installations?	NA	NA
	Comments:		
26.9	Routine checks of final exit doors and/or security fastenings?	✓	
	Comments:		
	Regular inspections are carried out by the caretaker to ensure that there are no hazards or		
	obstructions preventing a safe passage out of the building.		
26.10	Are systems in place for reporting and subsequent restoration of safety measures that	✓	
	have fallen below standard?		
	Comments:		
	The responsible persons, senior staff and the caretaker hold regular meetings to discuss		
	any downfalls in the fire safety strategies and standards.		
27	Records		
27.1	Appropriate records of:	-	
	Fire drills.	 ✓ 	
	Fire training.	\checkmark	
	Fire alarm maintenance.	\checkmark	
	Emergency lighting maintenance.	\checkmark	
	Firefighting appliance maintenance.		
	Maintenance and testing of other fire protection systems.	NA	NA
27.2	Comments:		
	The fire log book has been inspected and all entries are up to date.		
	A very thorough and well maintained log book.		
28	Review		
28.1	Comments:		
	A review of this risk assessment should be carried out periodically, the recommended		
	time line is generally every 12 months.		

	Photo Library
	Picture 1. The door from the reception class out onto the external stairs is in need of repair. Upon opening the bottom of the door catches on the floor.
<image/>	Picture 2. The Carbon Dioxide fire extinguisher seen here should be wall mounted using a suitable bracket.
	Picture 3. As these fire extinguishers within the office are not in the main school (away from the children) they should be raised to the recognized height of 100cm (handle to floor measurement). In addition identification signs should be displayed above each appliance.

Level of Fire Risk

The following simple fire risk level estimator is based on a commonly used health and safety risk level indicator.

Potential consequences of fire.	Slight harm	Moderate harm	Extreme harm
Low	Trivial risk	Tolerable risk	Moderate risk
Medium	Tolerable risk	Moderate risk	Substantial risk
High	Moderate risk	Substantial risk	Intolerable risk

Taking into account the fire protection measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Low	Medium	\checkmark	High	

In this context, a definition of the above terms is as follows:

Low: Unusually low likelihood of a fire as a result of negligible potential sources of ignition.

Medium: Normal fire hazards (e.g. potential ignition sources) for this type of occupancy. With fire hazards generally subject to appropriate controls (other than minor short comings).

High: Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in the likelihood of fire.

Taking into account the nature of the premises and the occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of a fire would be:

Slight Harm Moderate Harm	✓	Extreme Harm	
---------------------------	---	---------------------	--

In this context, a definition of the above terms is as follows:

Slight Harm: Outbreak of fire unlikely to result in serious injury or death of any occupants (other than an occupant sleeping in a room in which a fire occurs).

Moderate Harm: Outbreak of a fire could foreseeably result in injury (including serious injury) of one or more occupants, but it is unlikely to include multiple fatalities.

Extreme Harm: Significant potential for serious injury or death of one or more occupants.

Accordingly it is considered that the risk to life from fire at these premises is:

	Trivial		Tolerable	~	Moderate		Substantial		Intolerable	
--	---------	--	-----------	---	----------	--	-------------	--	-------------	--

Trivial: No action is required and no detailed records need be kept.

Tolerable: No major additional fire precautions required. However, there might be a need for reasonable practicable improvements that involve minor or limited cost.

Moderate: It is essential that efforts are made to reduce the risk. Risk reduction measures which should take cost into account, should be implemented within a defined time period.

Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improving control measures.

Substantial: Considerable resources might have to be allocated to reduce the risk. If the premises are unoccupied it should not be occupied until the risk has been reduced. If the premises is occupied, urgent action should be taken.

Intolerable: Premises (or relevant area) should not be occupied until the risk is reduced.

Note:

Although the purpose of this section is to place the fire risk in context, the above approach to the fire risk assessment is subjective and for guidance only.

All hazards and deficiencies identified in this report should be addressed, in order to reduce the risk of fire breaking out and the effects caused by a fire within the premises, by implementing all the recommendations contained in the following action plan.

Action Plan Colour Coding Reference

The time frame for each suggested action is based on its urgency, importance and ease to carry out. This is commonly known as the Traffic Light system.



	Action	n Plan
Section	Action	Date Completed & By Whom
	Make arrangements for the fixed electrical	
7.3	installations to be tested by a competent	
	person in accordance with the current IEE	
	Wiring Regulations.	
	Ensure that Portable Appliance Testing	
	(PAT) is scheduled for 2018.	
	Ensure that the Gas boilers are serviced by	
10.4	a competent person/company. The last	
	recorded maintenance inspection was in	
	2016.	
	Make provisions for the side gate to be	
16.4	kept unlocked during the working hours.	
	The means of securing the gate should	
	only be with the sliding bolts.	
	Repairs must be carried out to the exit door	
	within the Reception classroom leading out	
	to the external staircase.	
	Ensure that a decision is made regarding	
24.4	how the building will be checked in the	
	event of an evacuation.	
	Provide appropriate training if neccassary.	
	Display a fire exit sign indicating the	
19.2	alternative exit route out of the office area.	
	Fire Street	
	~	
	Contact your service provider regarding	
21.4	wall mounting the firefighting equipment	
	and raising brackets where indicated.	
0- 4	Ensure that fire warden training is brought	
25.4	up to date for all existing and new staff.	
	Continue to monitor the evacuation times	
25.5	during each fire drill. If the time taken	
	remains around 4 minutes the delays should	
	be looked into and if required the current	
0.0.1	evacuation plans should be reviewed.	
28.1	Make arrangements for the fire risk	
	assessment to be reviewed within the next	
	12 months	

Example of a fire safety maintenance check list:

Daily checks

- Remove bolts, padlocks and security devices from fire exits, ensure that doors on escape routes swing freely and that fire doors close fully and check escape routes to ensure they are clear from obstructions and combustible materials.
- Check the fire alarm panel to ensure the system is active, fully operational and that no faults are showing.
- Where practicable, visually check that emergency lighting units are in good repair and working.
- Check that all safety signs and notices are legible.

Weekly tests and checks

- Test fire-detection and warning systems and manually-operated warning devices weekly following the manufacturer's or installer's instructions.
- Check the batteries of safety torches and that fire extinguishers and hose reels are correctly located and in apparent working order. Fire pumps and standby diesel engines should be tested for 30 minutes each week.
- Inspect the fire log book, is it up to date.

Monthly tests and checks

- Test all emergency lighting systems and safety torches to make sure they have enough charge and illumination according to the manufacturer's or supplier's instructions. This should be at an appropriate time when, following the test, they will not be immediately required.
- Check that fire doors are in good working order and closing correctly and that the frames and seals are intact.
- Ensure housekeeping standards are met.

Six-monthly tests and checks

- A competent person should test and maintain the fire-detection and warning system.
- Carry out a full fire evacuation drill.
- Hold meetings with the responsible persons and site managers to discuss and review matters relating to fire safety.
- Make arrangements for the kitchen canopies, fans and filters to be cleaned professionally.
- Is the emergency plan still applicable to the building use?

Annual tests and checks

- The emergency lighting and all firefighting equipment, fire alarms and other installed systems should be tested and maintained by a competent person.
- All structural fire protection and elements of fire compartmentation should be inspected and any remedial action carried out.

Ensure that all staff receive fire safety and awareness training.

please note that some of the above may not be applicable to your building.

Example of what should be considered when writing an emergency procedure plan:

- What to do in the event of a fire
- Should residents adopt a stay put policy
- How to raise the fire alarm
- How to contact the fire brigade
- Who will take control in a fire situation
- Who is responsible for shutting down vital/dangerous equipment
- What dangerous equipment can be removed from site during an evacuation
- Where the fire exits are
- Who is responsible for checking the building
- How to check the building
- Who are the nominated fire wardens
- Contingency plans for any sleeping guests
- Who should liaise with the fire service
- Who is trained to use the firefighting equipment
- The location of the firefighting equipment
- A chart showing each fire zone of the building
- Important and useful phone numbers
- Individual staff roles

please note that some of the above may not be applicable to your building.

Fire hazards, elimination or control measures and relevant codes of practice

Fire Hazard Prompt List (Table 1)

This annex sets out a list of fire hazards that are normally considered in the fire risk assessment. Typical key measures for the elimination or control of each hazard are given, along with some relevant codes of practice or guidance documents. Government guidance documents in support of the relevant fire safety legislation also give guidance on those matters.

This prompt-list is not necessarily exhaustive, particularly in respect of measures for control and elimination of fire hazards, and there might be a need to consider further hazards and measures to prevent fire in the course of the fire risk assessment, particularly if work processes give rise to more specific fire hazards. Similarly, the codes of practice and guidance documents referenced are intended only to comprise a representative sample of those available.

Key factors to consider in assessment of means of escape (Table 2)

This table shows the key factors that should always be explicitly considered in assessment of means of escape. Most of the factors are quite broad and encompass a number of more specific issues.

These key factors can be used as a form of prompt-list and should, therefore, normally be shown in the documented fire risk assessment

Guidance on means of escape is contained in Government guidance documents that support the relevant fire safety legislation.

Fire hazards, elimination or control measures and relevant codes of practice

Table 1

Fire Hazard	Key measures for control or elimination of the fire	Relevant code of practice or guidance
Electrical faults	Periodic inspection and testing of fixed	IEE Guidance note [22].
	electrical installations	IEE Guidance of practice for in-service
	Portable appliance testing (PAT).	inspection and testing of electrical
	Employees and visitors use of their own	equipment [23].
	electrical equipment.	HSE HSG 107 [24].
	Reduction in the quantity of	Portable appliance testing:
	extension/trailing leads and adaptors.	www.hse.gov.uk/myth/july.htm
Smoking	Arrangements for those who wish to	
	smoke.	
	Prohibiting or limitation of smoking.	
Arson	Basic security measures to prevent	The prevention and control of arson [25].
	malicious ignition by outsiders.	
	Avoidance of unnecessary fire load in	
	close proximity to the premises.	
Improper use of	Avoidance of use of portable heating	
portable heaters	devices as far as being practical.	
	If portable heaters are to be used,	
	avoidance of the most dangerous type.	
	Suitable measures to minimize the	
	likelihood of ignition of combustible	
	materials.	
Faults in fixed	Regular maintenance of heating	
heating installations	installations.	
Use of cooking	Suitable design of cooking areas.	Cooking equipment [26].
appliances	Suitability of fire extinguishers to tackle	
	small fires.	Fire risk assessment-catering extract
	Regular removal & replacement of filters	ventilation.
Lighting	Drovide lighting protection systems if	DS EN 62205
Lignung	likelihood of a lighting strike	BS EN 02305
Contractora	Suitable fire sofety conditions in contracts	Standard fire presentions for contractors
contractors	with outside contractors	standard me precautions for contractors
works by	Suitable control over outside contractors	Fire prevention on construction sites
works by	while on the premises	[20]
maintenance starr	Suitable control over bazardous activities	Eire safety on construction [30]
	by in-house maintenance personnel such	The safety on construction [50].
	as hot-works involving cutting welding	
	or the use of blowlamps etc	
Poor housekeeping	Separation of combustible materials from	
and inadequate	ignition sources	
control over general	Avoidance of unnecessarv &	
fire hazards	inappropriate build up and storage of	
associated with work	waste or combustible materials.	
activities.	Appropriate storage of hazardous	
	materials.	
	Correct maintenance in the work place.	
	Routine safety inspections.	

Key factors and specific issues to consider in means of escape

Table 2	2
---------	---

Key factor	Specific issues to consider	Notes
Design of escape	Do escape routes lead to a final exit?	
routes	Do doors on the escape routes open in the	
	direction of travel?	
	Are doors on the escape routes fitted with	
	appropriate panic bolts or latches?	
	Will occupants of inner rooms be aware of a fire	
	within the premises?	
	Do any revolving or sliding doors have suitable	
	by-pass doors where necessary?	
Distances of travel	Are travel distances reasonable?	
	Are travel distances in dead ends suitably	
	limited?	
Protection of escape	Are escape routes, such as staircases, dead end	
routes	corridors, bedroom corridors etc., protected?	
	Are all fire resisting doors properly self-closing,	
	kept locked shut or only held open by suitable	
	correctly functioning automatic door release	
	mechanisms?	
Adequate provision of	Is there is sufficient number of fire exits and	
exits and escape routes	escape routes?	
	Are the number and widths of fire exits and	
	escape routes sufficient for the number of	
	occupants?	
Exits easily and	Are fire exits easily opened without the use of a	
immediately operated	key?	
(opened)	Is there only a single means of securing each fire	
	exit?	
	Where necessary do the means of securing fire	
	exits comprise of panic bolts or latches?	
	Where electronic locking devices are used, are	
	their use acceptable and the communication	
	between the secured door and fire alarm	
	monitored and maintained?	
Escape routes clear of	Are escape routes kept clear and unobstructed?	
obstructions and	Are adequate widths of corridors and any other	
hazards	escape route maintained at all times?	

Notes

APPENDIX 3

FIRE PROCEDURE – DESIGNATED ROUTES REGISTERS MUST BE TAKEN FROM CLASSROOMS OR FROM SCHOOL OFFICE BY SCHOOL SECRETARY/ADMINISTRATOR PLEASE NOTE THAT EACH TEACHING AREA DISPLAYS THE ROUTE BELOW Raise the alarm by setting off the fire alarm. When the bell rings, please leave in a calm and orderly fashion.
 Check all the rooms, lavatories, corners etc. Close all windows and doors as you leave the classroom. When outside do a head count and check the register.
Class 1 should leave by the fire escape and wait outside no 21
Class 2 should leave by the side passage and wait outside no 17
Class 3 should leave by the front door and wait outside no 15
Class 4 should leave by the front door and wait outside no 13
Class 5 should leave by the fire escape and wait outside no 25
Class 6 should leave by the front door and wait outside no 23
Class 7 should leave by the side passage and wait outside no 29
Reception should leave by the fire escape and wait outside no 27
Office staff and visitors leave via the side passage and assemble outside no 19
Staffroom leave through the side passage between no 19 and 21
Date reviewed: October 2017 – To be reviewed annually

Ace Fire Ltd – Your Complete Fire Protection Solution. Fire Extinguishers, Fire Alarms, Fire Risk Assessments, Fire Safety Training. Head Office. 14 Concorde Road, Norwich, NR6 6BW Tel. 01603 787333. Fax. 01603 787332. www.acefire.co.uk info@acefire.co.uk